

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Steven P. Ness

OREGON
JULY 14, 1997
STEVEN P. NESS
811

~~M 86-6~~ M 86-10
DATE: 10-29-80

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

East 1/4 Corner, Sec. 12, T24S, R2W, WM

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) None - A thorough
search for evidence was made after
the proportional position was determined.

No evidence was found of the two line
trees called, nor were any original
blazes found along the line. As
mentioned in my survey, topographic calls
were of no help in determining the corner's
position.

Accessories Found: (Condition and Source) None

#101 T24-24
#134 T24-14