

Mail:
1140 ACACIA LANE
GRANTS PASS, OR 97526

Office:
233 N. E. "B" STREET

M 96-58

ROBERT M. THOMPSON
Consulting Engineer, Surveyor, Forester

FILED *BS* TELEPHONE 476-3269
RECEIVED *BS*

MAY 30 1984

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

SURVEY TO LOCATE CERTAIN BOUNDARIES AND CORNER
IN THE N $\frac{1}{2}$ NW $\frac{1}{4}$ OF SECTION 33, T27S, R5W, W.M.,
DOUGLAS CO., OR.

Narrative Description to comply with Par. 209.250, O.R.S.

BY: Robert M. Thompson & Assoc., 1140 Acacia Ln., Grants Pass, OR 97527

FOR: Boise Cascade Corp., Timber & Wood Products Group, P.O. Box 100, Medford, OR
97501

PURPOSE: Find or establish the N.W. corner; mark the W $\frac{1}{2}$ of the North line,
and the north 1100'± of the North-South center line (to Southerly
edge of timber), in Section 33.

PROCEDURE:

Records of corner search and renewals, and past surveys were researched in the Douglas County Surveyor's Office. It was noted that many of the original Government Corners, in this portion of T27S, R5W, had been searched for, and not found. The original General Land Office (G.L.O.) Survey had been performed by Elder & Gile, in 1853. Additional search, and G.L.O. field note calls, not revealing any acceptable evidence of desired but missing corners, my survey used the following for control in setting the missing N.W. Section corner: the North $\frac{1}{4}$ corner and Southwest corner of Section 33, and the N.W. corners of Sections 28 and 32.

Using a Kern One Second Theodolite, and K&E Autoranger II E.D.M. equipment, supplemented by steel tape, a control traverse was run between the selected control corners, and the South $\frac{1}{4}$ corner of Section 33. After computation of the double proportioned position of the N.W. corner of Section 33, additional search was made for acceptable original evidence of same. Finding none, the corner was set in its computed position. The W $\frac{1}{2}$ of the North Section line, and approx. North 1100 feet of the North-South center line were then marked with red-painted blazes and red flagging, plus 1 $\frac{1}{2}$ "x5" "P/L BCC" aluminum tags. Corners found or set are as follows.

Corner Sections 20,21,28 & 29, C.S. File 49/62, fd. Co. Surv.

- 1959 brass cap on 1" G.I. Pipe, exp. 12", & B.T.'s:
- 26" W. Oak N 84°E 6.6', dim scribe vis., O.B.T.
- 24" W. Oak N 13°W 44.9' down, dead & rotted, old face, O.B.T.
- 8" W. Oak N 24°W 20.2', 1959, healed faces
- 26" B. Oak S 37°W 14.0' (rec.14.8'), 1959, healed faces
- 7" W. Oak S 41°E 14.9', 1959, healed faces
- 9" W. Oak N 28°E 27.6', 1959, healed faces

Corner Sections 29,30,31 & 32, C.S. File 53/38, fd. Co. Surv.

- 1970 brass cap on 1" G.I. Pipe exp. 14", at cor. of fences,
N & W, and Co. Surv.
- 1934-1938 B.T.'s, all with healed faces:
- 19" W. Oak S 76 $\frac{1}{2}$ °W 77.2'
- 17" W. Oak N 40 $\frac{1}{2}$ °W 57.3'
- 28" W. Oak S 5 $\frac{1}{2}$ °E 71.5'
- 19" W. Oak N 17°E 99.6' (rec. 98.4')

LAND SURVEYING

ROADS

BRIDGES

DAMS

TRACT DESIGN

FOREST MANAGEMENT

TIMBER CRUISING AND APPRAISAL

CS 58/275-4A

M 96-58

-2-

SURVEY TO LOCATE CERTAIN BOUNDARIES AND CORNER IN THE N $\frac{1}{2}$ NW $\frac{1}{4}$ OF SECTION 33, T27S, R5W, W.M., DOUGLAS CO., OR.

FILED BS
RECEIVED BS

MAY 30 1984

Corner Sections 28,29,32,33, Set by double proportionate meas.,

a 5/8" I. Rod w/Yel. Cap mkd. "Thompson", falls 6' So. of an E-W fence, scribed B.T.'s "T27S R5W S (No.) 1358 BT": I.R. 15 30" 1988
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

- 13" Ash S 41 $\frac{1}{2}$ °E 9.5'
- 16" Ash S 56 $\frac{1}{2}$ °W 19.1'
- 14" W. Oak N 19°W 30.8'
- 13" W. Oak N 47 3/4°E 68.8'

$\frac{1}{4}$ Corner Sections 28/33, C.S. File 53/38, fd. Co. Surv. 1963

brass cap on 1" G.I. Pipe exp. 12", 9' S'ly. of cor. of fences

N.S, & W, & B.T.'s:

- 20" B. Oak S 33°E 9.2', rotted face, O.B.T.
- 24" B. Oak N 13°E 9.2', rotted face, O.B.T.
- 16" D. Fir S 68°W 40.0', base, (rec. 39.5'), 1963, healed faces
- 14" B. Oak N 75°W 41.5', 1963, healed faces

Corner Sections 32/33, C.S. File 57/36, fd. Co. Surv. 1974

brass cap on 1" G.I. Pipe exp. 8", & B.T.'s:

- 30" D. Fir N 42°E 5.3' face opened, scribe vis., O.B.T.
- 13" I. Cedar N 24°W 8.8', scribe vis., 1974

Note, cor. falls on a small cutover ridge, brs. N'ly, approx. 250' N'ly of logg. rd., E'ly & W'ly. Both B.T.'s are 6' high sawed stumps. No trees suitable for add. B.T.'s within reasonable distance.

South $\frac{1}{4}$ Corner Section 33, C.S. File 49/64, fd. Co. Surv.

1961 br. cap on 1" G.I. Pipe exp. 14", near W'ly edge of open meadow, 60.7' W'ly of cor. of fences brg. N,S,E, & B.T.'s:

- 12" B. Oak N 37°W 133.3', snag w/scribe vis.
- 38" B. Oak N 15 $\frac{1}{4}$ °E 180.8', O.B.T. w/1961 rescribe healed

May 21, 1984

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Albert M. Thompson

STATE OF OREGON
ROBERT M. ...

C.S. File No. 58/275(N) - 4b