

CORNER RESTORATION - INTERNATIONAL PAPER COMPANY

FILED
RECEIVED *JH*
SEP 10 1982

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

SEC CORNER T22S-R9W
 33 | 34
 4 | 3
 T23S-R9W

FOUND: Iron fence post which had been placed, by me, along side corner monument in 1980.
 Five BT's listed below.

SET: Drove Douglas County Surveyor's 30"x1" g.i.p./b.c., 1967, which had been removed by IPCo cutting crew, alongside the fence post from which:
 34" D-fir stump, with IPCo tag, bears N35°E, 23.5 ft.
 6" burnt hemlock stob, with IPCo tag, bears S29½°E, 77.0 ft.
 14" hemlock stump, with IPCo tag, bears S14¼°W, 78.7 ft.
 42" D-fir stump, with IPCo tag, bears S27°W, 57.3 ft.
 15" hemlock stump, scribing visible, with IPCo tag, bears N01°W, 34.4 ft.

BT's in Sec 3 and 4 treated with pentachlorophenol and covered with galvanized metal.

88 T22-9W
90 T23-9W

C

CW/js

Carey Weather, Field Engineer

