

CORNER RESTORATION - INTERNATIONAL PAPER COMPANY
(AUGUST)

FILED
RECEIVED
SEP 10 1982

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

LOT CORNER $\frac{3|2}{7|8}$ ✓ Sec 3, T20S-R10W, W.M.

- FOUND: No evidence of 5/8" I.R. set by Hintz (1977) lost in logging.
30" D-fir stump BT, face evident, nail in root collar, BLM tag reads N25°E, 26.7 ft. (Hintz 1977)
20" D-fir stump BT, face evident, nail in root collar (Hintz 1977).
- SET: 1-3/8" Galvanized iron pipe with brass cap marked "C, 1/16, S3, 80 1982, LS 1667"
30" D-fir stump BT, face evident, nail in root collar, BLM tag, bears S25°W, 26.7 ft.
20" D-fir stump BT, face evident, nail in root collar, IP tag, bears S14°E, 18.1 ft.

1/4 CORNER SEC 9|10 T20S-R10W, W.M.

- FOUND: No evidence of 1952 BLM monument.
30" D-fir BT, marked by BLM in 1952 now a 36" D-fir stump with IPCo tag reading N87°W, 44.6 ft.
14" maple BT, marked by BLM in 1952 gone.
78" D-fir stump with IPCo tag reading S45°W, 37.7 ft.
- SET: 1-3/8" galvanized iron pipe with brass cap marked "Sec 9|10, T20S-R10W, 1982, LS 1667" from which:
36" D-fir stump, with IPCo tag, bears S87°E, 44.6 ft.
78" D-fir stump, with IPCo tag, bears N45°E, 37.7 ft.
18" Maple stump, with IPCo tag, bears S84½°W, 56.1 ft.

73

SEC CORNER $\frac{9|10}{16|15}$ T20S-R10W, W.M.

- FOUND: 1-1/2" galvanized iron pipe with 1952 BLM brass cap in good condition.
36" D-fir BT (BLM 1952), now a 36" stump with IPCo tag reading S77°W, 6.0 ft.
56" D-fir BT, face evident (BLM 1952), now a 56" stump with IPCo tag reading N28°W, 9.4 ft.
28" hemlock BT (BLM 1952) now a 34" stump with IPCo tag reading ~~S75½°W~~ N75½°E, 45.4 ft.
20" alder BT (BLM 1952) now a 20" stump.
44" D-fir stump with IPCo tag reading N51°W, 57.0 ft.
- SET: IPCo tag, on 20" alder stump BT, reads S33°E, 23.8 ft.

9/10/82
Z.H.
PER W.E.
WEATHERLY

74