

M 96-63 AEB

FILED
RECEIVED *BL*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 28 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Original GLO 1891 Thiel


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.

Sketch



Monument Set (Procedures and Description)

Position determined from record latitude South from the 1/4 28/27 and record departure East from the S.W. corner Section 28, per BLM recommendation.

New Accessories

7" D. Fir bears N 67° W 6.9 ft., scribed T21S R11W S28 BT

7" D. Fir bears N 21° E 26.9 ft., scribed T21S R11W S27 BT

Location & Comments

Set from survey for U.S. Forest Service

Compass Declination 19°50'E

Firm/Agency _____

Jackson & Prochnau, Inc.

Address P.O. Box 177

Albany, Ore. 97321

Party Chief K. Kendall

Notes _____

Witness Larry Griensewic

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

© #184