

M 96-64 A, B

FILED
RECEIVED *BS*

OREGON CORNER RESTORATION FORM


JUN 6 1984

Section 33 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-16-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Original GLO 1891 Thiel (corner never set)


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Set 3" alum. cap in 2 1/2" x 30" alum. pipe with flared base, rockmound.

Sketch



Monument Set (Procedures and Description)

Position determined at midpoint in departure between the NE and NW corner of Section 33, and on line between the SW corner, Section 28 and the S 1/4 Section 28.

New Accessories

18" Alder bears S 63° E 16.2 ft., bark scribed 1/4 S33 BT
28" D. Fir bears S 31° W 47.9 ft., scribed 1/4 S33 BT

Location & Comments

Surveyor's Seal

Set from survey for U.S. Forest Service Compass Declination 19° 50' E
 Firm/Agency Jackson & Prochnau, Inc.
 Address P.O. Box 177
Albany, Ore. 97321
 Party Chief K. Kendall
 Notes _____
 Witness Larry Griensewic

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

187

6

C.S. File No. 58/274-SF