

M 96-65 AEB

FILED
RECEIVED BS

JUN 6 1984


OREGON CORNER RESTORATION FORM

Section 34 Township 21S Range 11W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 4-13-84

Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____
Original GLO 1891, Thiel (corner never set)


Monument(s) & Accessories Found: (Condition and Source)

NONE

Monument Detail

Sketch

Set 2" alum. cap on $\frac{1}{2}$ " x 30" iron rod, rockmound.



Monument Set (Procedures and Description)

Set at midpoint in departure between the NW corner and the NE corner, on line between SW corner of Section 27 and the S $\frac{1}{4}$ corner of Section 27.

New Accessories

32" D. Fir bears S 43° E, 13.9 ft., scribed $\frac{1}{4}$ S34 BT
6" Alder bears S 14° W, 17.1 ft., bark scribed $\frac{1}{4}$ S34 BT

Location & Comments

Surveyor's Seal

Set from survey for U.S. Forest Service Compass Declination 19°50'E
Firm/Agency Jackson & Prochnau, Inc.
Address P.O. Box 177
Albany, Ore. 97321
Party Chief K. Kendall
Notes _____
Witness Larry Griensewic

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James W. Prochnau

OREGON
SEPTEMBER 21, 1977
JAMES W. PROCHNAU
1305

#182

11

C.S. File No. 58/294-6K