

FILED
RECEIVED

MAR 15 1985

OREGON CORNER RESTORATION FORM

Section 4 Township 32.5 Range 5W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 3/13/85

Corner Designation

N 1/16 5/4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

1962 Cadastral Resurvey

Monument(s) & Accessories Found: (Condition and Source)


B.C. in mound of rock

40" DF N88E 128" OBT Stamp

17" Fir N57W 55" OBT. Gene road has been built in area,

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

6" DF West 15" scribed "N 1/16 S 5 BT"

5" DF S 111 E 41" scribed "N 1/16 S 4 BT"

Location & Comments

Corner is on
SE edge of
road tunneling
NE - SW

Compass Declination 20°

Firm/Agency _____

Roseburg Lbr. Co.

Address P.O. Box 1088

Roseburg Lbr. Co.

Party Chief How Johnstone

Notes _____

Witness Lew Howe

Surveyor's Seal

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Howard W. Johnstone

OREGON
 MAY 13, 1980
 HOWARD W. JOHNSTONE
 498