

Section 4 Twp 21S Rge 11 W

Date: Jan 27 1975

How was corner identified? Found BCIP 1/4 Corner Section 4-9

T21S R11W; Found BT 14" Douglas Fir Bears N 55° 15' W  
@ Dist of 11 1/2 ft.

Condition of corner: BCIP in good shape

Best route to reach corner: \_\_\_\_\_

Scribed 2 new BT's

Other Remarks:

<del>Quadrant</del>	<del>NB</del>	<del>NW</del>	<del>SE</del>	<del>SW</del>
<del>Species &amp; Size</del>	<u>14" Douglas Fir Bears N 9° 45' E Dist 23<sup>2</sup></u>			
<del>Dist. &amp; Bearing</del>	<u>Scribed (T21S, R11 W S 1/4 S4)</u>			
<del>Condition of Scribe</del>				
<del>Original or Resurvey</del>	<u>14" Douglas Fir Bears S 9° 30' E Dist. 49<sup>2</sup></u>			
<del>Appearance of B.T.</del>	<u>Scribed (T21S, R11 W N 1/4 S9)</u>			
<del>Tags, Marks, etc.</del>				

Robert B. Ward  
 Forest Engineer Signed  
 U.S. Plywood Madleton, Ore.

59/2.1