

RENEWAL

S4 53  
CC  
T205 R9W

(SEE RENEWAL NO. 13)

FOUND

38 (REC. 48) INCH

DIAMETER FIR STUMP.

STUMP IS ROTTED, PARTIAL SCRIBING  
VISIBLE, "CC S3 BT". STUMP  
BEARS S 27° E, 45 ± FEET.

BRASS CAP NOT FOUND

RENEWAL

1. SET BRASS CAP AT CLOSING CORNER  
STAMPED

" COUNTY SURVEYORS OFFICE "

T 195 R 9 W

S 34

S 4 53

C. C.

T 205 R 9 W

1976

2. SET SPIKE IN 43 INCH DIAMETER

FIR STUMP. SPIKE BEARS S 39° W,  
118 ± FEET, SPIKE STAMPED "B.O."

#26

C. S. File No. 59/2-9

DIETZEN N. O. 8955-6

RENEWAL

SA/83

PC

TRO SR9W

THEY THERE ARE NO SUITABLE  
TREES FOR SCRIBING IN THE  
SOUTHERLY QUADRANTS. CORNER  
FALLS IN A STEEP SLIDE AREA.

MAG. REC.

1 - 20 - 76

L. E. MONREAN

D. L. EARLE

J. H. COOK

OK  
~~EARLE~~