

2-11-75

$\frac{23}{26}$ $\frac{1}{4}$

T 295 B 1 E

Fp:

REMAINS OF ORIGINAL NW BEARING, AN
ORIG. 12' D. FIR NOW A 15" ROTTED STUMP
WITH SCRIBING "T" VISIBLE.

WE ALSO FIND THE ORIGINAL MONUMENT, A
15" X 8" X 6" STONE WITH " $\frac{1}{4}$ " CHISELED ON
APPARENT NORTH FACE. THIS STONE HAS
BEEN DISTURBED BY LOGGING ACTIVITY.

WE FIND THE PROBABLE REMAINS OF THE ORIG.
SE BEARING TREE BUT CANNOT POSITIVELY
IDENTIFY IT.

AT THE CORNER POINT AS DETERMINED BY
RECORD BEARING AND DISTANCE FROM
THE REMAINS OF THE ORIGINAL NW BEARING
TREE, AN ORIG. 12" FIR, NOW A 15" ROTTEN STUMP,
BEARING N 46° W. 6 ± FT., WE SET A 1" X 30"
IRON PIPE, 26" IN THE GROUND WITH BRASS
CAP ATTACHED, MARKED:

~~59/2-16~~
ON 02-15-75

DOUGLAS CO. SURVEYOR

T295 E 1 E

$\frac{1}{4}$ S 23
S 26

1976

WE PLACE THE ORIGINAL STONE ALONGSIDE THE SOUTH EDGE OF THE BRASS CAP WITH THE " $\frac{1}{4}$ " FACING WEST, AND MARK THE FOLLOWING BEARING TREES

A 12" INCEASE CEDAR BEARS N 75 $\frac{1}{2}$ ° E 49 $\frac{1}{2}$ FT.,
SCRIBED " $\frac{1}{4}$ S 23 CS BT" ON A DOUBLE BLAZE.

AND A 7" G. FIR BEARS N 22° W 32 $\frac{1}{2}$ FT.,
SCRIBED " $\frac{1}{4}$ S 23 CS BT" ON A DOUBLE BLAZE.

NOTE:

2-11-76

OK

THIS CORNER IS LOCATED

APPROX. 150 FT. ~~FROM~~

Bary J. Langlet
CLELL E. GOODWIN

WEST OF THE EAST EDGE
OF AN OLD CLEARCUT

M. LENORA LADIG

A. VIC. CANGIE

UNIT.

C.S. File No. 59/2-16

(SEE NEXT PAGE) →

DIETZGEN NO. 385-B

WE ALSO PLACE A LOCATION TAG APPROX.
550 FT. WEST OF THE $\frac{1}{4}$ CORNER NEAR THE
END OF FOREST SERVICE ROAD # 2921-D.

DIETZGEN NO. 385-6

S.S. FILE NO. ~~59/2-16~~