

T 305 R 3W
S18 S17
S19 S20

(SEE RENEWALS 36, 57,
& 160)

FOUND

1. 1 INCH DIAMETER

IRON PIPE SET

IN 1950 (SEE RENEWAL NO. 36). IRON
PIPE IS FIRMLY IN PLACE, AN APPROX.
36 INCH DIAMETER LOG LYING OVER
MONUMENT.

FROM WHICH

(ORIGINAL B.T.S)

2. A FIR STUMP, IS NOW 36 INCH
DIAMETER, BEARS S 78° W, 44²
FEET. BLAZE HAS BEEN OPENED,
SCRIBING "BT" LEGIBLE.

3. A FIR, UPROOTED AND BADLY ROTTED,
APPROXIMATE STANDING POSITION
BEARS S 18° E, 9² FEET. TREE HAS
SCAR WHICH HAS BEEN OPENED,
NO SCRIBING VISIBLE.

4. A MAPLE, 6 NOW 20 INCH DIAMETER
BEARS N 19 1/2° E, 43⁶ FEET (REC N 18° E)
TREE BLAZED, ORIGINAL BLAZE BADLY

206

C.S.M.

59/2-18

ROTTED, SCRIBING "CS" LEGIBLE
FROM RE SCRIBE PER RENEWAL NO. 36.

ORIGINAL N.W. B.T. NOT FOUND.

(B.T. PER RENEWAL NO. 36)

5. A 12 NOW 13 INCH FIR STUMP,
BADLY ROTTED, BEARS N 28° W,
56 1/2 FEET (REC. 58 1/2 FEET).
SCRIBING VISIBLE "18 CS BT".

6. A 16 NOW 26 INCH DIAMETER RED CEDAR
BEARS S 29° E, 42 1/2 FEET (REC.
S 31° 20' E). TREE HAS GOOD
BLAZE.

(B.T. PER RENEWAL NO. 160)

7. A 24 INCH DIAMETER RED FIR,
BEARS S 44° W, 80 1/2 FEET (REC.
81 1/2 FEET). TREE HAS GOOD
BLAZE, PITCHED OVER.

RENEWAL

1. SET BRASS CAP AT SECTION
CORNER, STAMPED;

"COUNTY SURVEYORS OFFICE"

T30S R3W

S18 | S17

S19 | S20

1976

1 INCH IRON PIPE ALONG SIDE.

NEW BEARING TREES

2. DOUGLAS FIR, 9 INCH DIAMETER,
BEARS N 58 1/2° W, 51 1/2 FEET.

TREE BLAZED AND SCRIBED

"T30S R3W S18 CS BT"

3. A RED FIR, 40 INCH DIAMETER,
BEARS N 48 1/2° E, 48 FEET.

TREE BLAZED AND SCRIBED

"T30S R3W S17 CS BT"

MAG. DEC. 20° E 1-22-76

~~OK~~

L. E. MONREAN

P. L. EARLE

J. H. COOK

G.S. FILED 09/2-18

DIETZEN NO. 385-B