

T 235 RSW

RENEWAL 55134

SEE RENEWAL NO. 51, 54

FOUND

BRASS CAP SET

BY COUNTY IN 1959

CAP IS OUT OF GROUND

ON EDGE OF ROAD, CAP STAMPED

"COUNTY SURVEYORS OFFICE"

T 235 RSW

55 | 54

T 235

1959

DILTZEN NO. 385-6

ORIGINAL 18 NOW 38 INCH DIAMETER

2. FIR STUMP BEARS S 58° E, 33°

FEET, STUMP SCRIBED "RSW T235

4"

12 NOW 16 INCH DIAMETER RED FIR

3. BEARS S 45° E, 68 ± FEET (REC.

89 ± FEET). TREE HAS GOOD

BLAZE, TAGGED.

#100 T23-5 ✓
#163-722-5 ✓

C.S. File No. 59/B-1C

1235RSW

25/34

FOUND

4. B NOW 11 INCH DIAMETER RED
FIR BEARS S 16 1/2° W, 14° FEET
(REC. S 19° W) TREE HAS
GOOD BLAZE, TAGGED.

RENEWAL

RE SET BRASS CAP AT SECTION
CORNER, CAP STAMPED AS
NOTED. CORNER LIES ON
EDGE OF ROAD. SET FENCE
POST AND SIGN BESIDE MONUMENT.

MAG. DEC. 20° E 2-18-76

L. E. MONREAN

J. H. COOK

OK *[Signature]*

DIETZEN NO. 385.6

#100

C. S. File No. 59/8-1c