

3/23-76

T29S R9W

①

SA | SB

(SEE #68)

FOUND:

A 15" NOW 24" CEDAR (ORIGINAL NE, BEARING TREE) ALREADY OPENED.

SCRIBE MARKS FROM ORIGINAL

SURVEY AND RENEWAL DONE

BY CLAUDE KERR (SEE #68)

BOTH VISIBLE AND IN DIFFERENT

DEPTHS IN TREE. TREE IS ALIVE.

AND IN FAIR CONDITION BEARING  
N41E AND 19.1' DIST.

A 22" HEMLOCK RECORDED IN 1960

(SEE RENEWAL #68) TO BS 28".

I FIND THE RECORDED BEARING

AND DISTANCE TO BE IN ERROR

AND CHANGE IT FROM SE 8° W

35.7' TO S56° W 43.2'. TREE

IS ALIVE AND WELL. SCRIBING

VISIBLE.

I FOUND NO TRACE OF OTHER

BEARING TREES OR MONUMENT.

DIETZGEN NO. 385-6

#81-T29-9v

C. S. File No. 59/8-11 C

T 29 S R 9 W

SA | SB

(1)

AT THE CORNER POINT ESTABLISHED FROM ORIGINAL 15" CEDAR I SET A 1" X 30" IRON PIPE WITH BRASS CAP STAMPED:

DOUGLAS CO, SURVEYOR

T 29 S R 9 W

1/4 COR

SA | SB

1976

NEW TREES:

A 19" HEMLOCK BEARS S 4° W

17.8' DISTANCE AND MARKED

"1/4 S 4 CS BT" IN A DOUBLE

BLAZE.

COMPASS DEC.

20° E

A. J. [Signature]

Jim H. Cook

OK [Signature]

C. S. File No. 52/8-11

DIETZGEN NO. 3855-6