

8-18-76

26 | 25

27 | 28

T 28 S R 4 W

(SEE REN. # 58)

FD:

A  $\frac{5}{8}$ " IRON ROD, SET FLUSH IN THE GROUND AS NOTED BY MARKHAM IN REN. # 58.

FROM WHICH:

A 34" D. FIR BEARS S 69° E 16  $\frac{5}{8}$  FT., WITH MARKHAM'S RESCRIBING "S 36" PLAINLY VISIBLE IN THE BARK. RENEWAL # 58 NOTES THIS TREE AS BEING AN ORIGINAL BEARING TREE, BEARING S 73° E 15  $\frac{1}{2}$  FT., AND HAVING SCRIBING VISIBLE IN THE BARK. WE FIND NO TRACE OF AN OLD BARK SCRIBE, THEREFORE WE OPEN THE TREE TO THE PROPER DEPTH AS INDICATED BY THE GROWTH RINGS AND DO NOT FIND ANY EVIDENCE OF AN OLD BLAZE.

A 36" D. FIR BEARS S 9° W 24  $\frac{1}{2}$  FT. WITH MARKHAM'S BARK RESCRIBING "S 35" PLAINLY

NOTED ✓

G. S. File No. 59/18-18

PAGE 1

100° @ 28°

88

98° @ 31°

84

55 @ 24

50

10 LVL

10

232

VISIBLE. RENEWAL #58 NOTES THIS TREE AS AN ORIGINAL BEARING TREE, HOWEVER WE FIND NO EVIDENCE OF THE ORIGINAL ~~MARKS~~ TREE MARKINGS. ORIGINAL BEARING AND DISTANCE IS  $S 5^{\circ} W$  25 FT.

WE FIND NO TRACE OF ANY OTHER ORIGINAL LOCATION EVIDENCE.

RENEWAL #58 NOTES THE FOLLOWING ADDITIONAL BT'S:

A 5" FIR, NOW AN 8" HEMLOCK, ALIVE AND WELL-HEALED BEARS  $N 30^{\circ} W$  2 FT.

AND AN 18" NOW 23" CEDAR BEARS  $S 84^{\circ} E$  40 FT. (RECORD PER REN. #58;  $S 88^{\circ} E$  39 FT.) WITH ILLEGIBLE SCRIBING VISIBLE ON UNHEALED BLAZE.

IT IS NOT POSSIBLE TO RECONCILE THE CONDITIONS FOUND ON THE GROUND WITH EITHER THE NOTES OF THE ORIGINAL SURVEY OR RENEWAL #58. WE LEAVE THE CORNER INTACT AS FOUND.

B-18-76

*[Signature]*

JAMES H. COOK

C.S. File No. 5918-18

*[Signature]*

KAREN CHENEY