

DLC-54

SE COR.

SEE PGNS. 125 & 29

T285 R7W

FOUND:

A $3\frac{1}{4}$ " x 29" IRON PIPE FROM WHICH:
AN ORIGINAL 10" D.F. NOW 23"

SNAG BEARS N20°W; 24.4' TREE
SHOWS LARGE DEEP HEALED SCAR.

A 16" MAPLE BEARS S46°E; 12.4'
FACE IS ROTTED OUT AND TREE
IS DYING.

A 24" NOW 34" W.F. BEARS N76°W;
9.3' TREE IS ALIVE & SHOWS
GOOD SCAR.

SET:

A 1" x 30" BRASS CAP STAMPED
DOUGLAS CO. SURVEYOR
DLC 54

SE. COR.

T285 R7W

1976

G. S. File No. 59/18C

#231 ✓

8126176

DLC SA

SEE REFS. 29 & 125

SE. COR.

T285 R7W

(2)

REPLACED FOUND IRON P.P.
ON EAST SIDE OF BRASS CAP.

NEW TREES:

A 6" D.F. BEARS N 2 1/2° E; 15.1'
MARKED "SE DLC SA CS BT" IN
A DOUBLE BLAZE.

A 9" D.F. BEARS S 35 1/2° E; 33.5'
MARKED "SE DLC SA CS BT" IN
A DOUBLE BLAZE

COMPASS DEC. 20° E

A. J. [unclear] [unclear]

KAREN CHENEY

OK
[Signature]

DIETZGEN NO. 385-6