

T 2 B S R 7 W

S S S S

S B S S

SEE RENEWAL #144

FOUND:

NO TRACE OF BRASS CAP SET IN
1924. DID NOT FIND ANY ORIGINAL
OR 1924 RESURVEY BEARING TREES.

I DID FIND 3 BEARING TREE FROM
THE 1961 RENEWAL STILL STANDING
FROM WHICH I SET A BRASS CAP
AFTER OPENING A WHITE OAK
AND FINDING SCRIBING "T 2 B S R 7 W
S S S S" ON THE UPPER BLAZE.

RENEWAL

SET BRASS CAP AT SECTION CORNER
STAMPED;

"DOUGLAS COUNTY SURVEYOR'S OFFICE"

T 2 B S R 7 W

S S S S

S B S S

1976

#232 ✓

G. S. File No. 59/24 C

FROM WHICH

(TREES PER REVEALAL 144)

A W. OAK 6 NOW 8 INCHES
DIAMETER BEARS N 41° E, 27 $\frac{1}{2}$
FEET. TREE DOUBLE BLAZED AND
SCRIBED "T28SR7W54CS" ON
UPPER BLAZE, THE LOWER
BLAZE IS WELL HEALED.

A W. OAK 5 NOW 7 INCHES DIAM.
BEARS N 19° E, 23 $\frac{1}{2}$ FEET. TREE
HAS WELL HEALED DOUBLE BLAZE.

AN R. FIR 18 NOW 24 INCH DIAM.
BEARS S $2\frac{1}{2}^{\circ}$ E, 56 $\frac{1}{2}$ FEET (REL.
S $5\frac{1}{2}^{\circ}$ E). TREE HAS WELL HEALED
DOUBLE BLAZE.

A CEDAR 18 INCH DIAMETER, NOW
A WINDFALL, BEARS S $61\frac{1}{2}^{\circ}$ W,
49 $\frac{1}{2}$ FEET. TREE LAYING WITH
BLAZE DOWN.

NEW BEARING TREE

2 AN I CEDAR, 7 INCH DIAM. BEARS
N 65 1/2° W, 26' FEET, TREE
DOUBLE BLAZED AND SCRIBED
"TZBSR7WSSCSBT".

MAG. DECLINATION

10-4-76

20° E

L. E. MONREAN

P. L. EARLE

OK
[Signature]

DIETZGEN NO. 385-6

U. S. File No. 59/29-22