

RENEWAL

10-25-76

M. C.

S1/S6

(1)

T22S

R11W R10W

FB:

A 2" x 30" IRON PIPE WITH PUMP
BELL .3 FT BELOW GROUND IN
MARSHY AREA

A 50" DIAM SPURCE BEARS S. B^oE.,
111.5 FT. DIST. WITH RE-SCRIBING
BY BAUGHMAN "S6 MC ST"

(SEE C.S. FILE M56-56)

CENTER ROTTED, TOP DEAD, WITH
CREEK (COURSE N-NW) UNDER TREE.

NO OTHER ORIGINAL TREES FOUND

SEL:

A 1" x 30" IRON PIPE WITH
BRASS CAP, 27 INS. IN GROUND
MARKED:

DOUGLAS Co. SURVEYOR

T.22S.

R M. C. R

11 S1 | S6 10

W W

#77 T22-10V

#146 T22-11V

1976

C.S. File No. 59/24-C

DIETZEN NO. 3885-6

RENEWAL

10-25-76

M.C.

S1/S6

(2)

T225

R1W, K1W

CAP SET IN POSITION OF FD,
PIPE AS PER BEARING AND DIST.
FROM FD, ET.

CAP SET IN MOUND OF STONE
1 1/2 FT. DIAM AND 1 FT. BELOW
SURFACE OF GROUND.

CAP STANDS .3 FT ABOVE GROUND.

PLACE IRON PIPE ON N. EDGE OF
CAP.

COR. FALLS IN OLD N-S FENCE
LINE.

SET SIGN AND POST 2 FT SOUTH
OF COR., 3/2 INS. ABOVE GROUND.

NO OTHER BT'S AVAILABLE FOR
SCRIBING IN WEST QUADS.

DECLINATION

20° EAST

K. CHERRY

L. E. MOURREAU

OK
U.S. File No. 59/24-A2