

RENEWAL

11-2-76

T 30 S R 5 W

SOUTH EAST CORNER

D.L.C. NO. 42

FOUND

1. ORIGINAL 12 NOW 36 INCH DIAM.
W OAK. TREE BEARS N 30° W,
96[±] FEET. TREE HAS BEEN
PREVIOUSLY OPENED, CENTER
PARTIALLY ROTTED. I OPEN TREE
BELOW CHOPPED OUT PORTION AND
FIND FRAGMENTARY REVERSE
SCRIBING ... "8" ...

2. NOT OF RECORD, A 3/4 INCH DIAM.
IRON PIPE FROM WHICH ORIGINAL
BEARING TREE BEARS N 27° W,
96^L FEET.

RENEWAL

1. SET 1" X 30" IRON PIPE WITH BRASS
CAP ATTACHED AT D.L.C. CORNER

#272✓

U.S. File No. 59/26

RENEWAL

CAP IS STAMPED;

" DOUGLAS COUNTY SURVEYOR "

T 30 S R 5 W

S. E. COR.

DLC # 42

1976

FROM WHICH

2. ORIGINAL W. OAK BEARS N 30° W,
96 ± FEET.

3. A B. OAK 50 INCH DIAMETER BEARS
S 65° E, 77² FEET. TREE DOUBLE
BLAZED AND SCRIBED " T 30 S R 5 W
SE DLC 42 CS BT ". BEARING
AND DISTANCE RECORDED TO CENTER
OF BASE.

4. 3/4 INCH DIAMETER IRON PIPE BEARS
S 56 3/4° W, 4³ FEET.

MAGNETIC DECLINATION 20° EAST

11-2-76

L. E. MONREAN

P. L. EARLE

C. S. File No. 59/26

ORIGINAL NO. 385-6

S 65° E

812 @ 17½° = 779