

$$43^{\circ} \text{ @ } 14^{\circ} = 41^{\circ}$$

$$\begin{array}{r} 9703 \\ \underline{43} \\ 29109 \\ 33812 \\ \underline{} \\ 417229 \end{array}$$

$$18^{\circ} \text{ @ } 20^{\circ} = 17.6^{\circ}$$

$$\begin{array}{r} 9397 \\ \underline{.187} \\ 65779 \\ 75176 \\ 9397 \\ \underline{} \\ 17.57239 \end{array}$$

$$\begin{array}{r} .6 \quad .12 \\ \underline{.2} \quad \underline{.6} \\ 7.2 \\ \underline{} \\ 1.9 \\ \underline{} \\ .6 \\ \underline{} \\ 1.4 \end{array}$$

$$17^{\circ} \text{ @ } 17^{\circ} = 16.8^{\circ}$$

$$\begin{array}{r} 9563 \\ \underline{17.6} \\ 57378 \\ 66741 \\ 9563 \\ \underline{} \\ 16.81088 \end{array}$$

$$\begin{array}{r} .44 \\ \underline{1.8} \\ 352 \\ \underline{44} \\ 79 \end{array}$$

THE EXISTENCE OF THIS BT IS FIRST NOTED
IN 1882 BY U.S. DEPUTY SURVEYOR SAM C.
FLINT.

THE FOLLOWING BT'S WERE MARKED BY BLM
IN 1958:

A 6" NOW 7" D. FIR, ALIVE AND WELL-HEALED
BEARS N 51 1/2° E 17 3/8 FT.

A 23" NOW 26" D. FIR, ALIVE AND WELL-HEALED
BEARS S 46° E 7 3/8 FT.

AN 18" D. FIR, NOW A 19" STUMP, WELL-HEALED,
BEARS S 76° W 16 5/8 FT..

AND A 10" D. FIR, NOW A 12" STUMP, WELL-HEALED,
BEARS N 24° W 41 7/8 FT., (REG. N 24° W 42 3/8 FT.)

NOTE:

A NEW CLEARCUT UNIT IS ADJACENT TO AND
WEST OF THIS CORNER.

MAGNETIC DECLINATION: 20° EAST

11-3-76

OK *[Signature]* Gary J. Langlet
KAREN CHENEY

DIETZEN NO. 385-6