

RENEWAL

T 21 S R 11 W

56	55
57	58

SEE RENEWAL NO. 40

FOUND

1. BADLY DECAYED STUMP OF ORIGINAL CORNER TREE

2. BRASS CAP SET BY D.C.S.O. 1967 BEARS WEST 1 1/2 FEET FROM CENTER OF ORIGINAL CORNER TREE STUMP. CAP IS STAMPED,

"COUNTY SURVEYORS OFFICE"

T 21 S

56	55
57	58

R 11 W

1967

NOTE; BEARINGS AND DISTANCES RECORDED BELOW ARE FROM THE D.C.S.O. BRASS CAP, NOT THE ORIGINAL CORNER TREE STUMP.

#87 ✓

T 215 R 11 W

$\frac{6}{7} \frac{5}{8}$

3. ORIGINAL 10 NOW 26 INCH DIAM.
CEDAR BEARS N $17\frac{1}{2}^{\circ}$ E, 14² FEET
1967 RESCRIBE ON OPEN BLAZE
"T 215 R 11 W S 5 CS BT".

4. ORIGINAL 42 INCH ~~S~~ FIR, NOW A
46 INCH DIAM. STUMP BEARS
N $17\frac{1}{2}^{\circ}$ W, 20¹ FEET. HAS
GOOD SCAR, I DID NOT OPEN.

5. A CEDAR, 36 INCH DIAMETER BEARS
S $16\frac{1}{2}^{\circ}$ W, 30⁴ FEET. TREE HAS
OPEN BLAZE, SCRIBING VISIBLE
"T 215 R 11 W S 7 CS BT".

6. A CEDAR 40 NOW 44 INCH
DIAMETER, BEARS N 43° W, 26²
FEET. TREE HAS OPEN BLAZE,
SCRIBING VISIBLE "S R 11 W S 6 W".
TREE NOT SCRIBED BT AS
RECORDED.

RENEWAL

TO THE 44 INCH DIAM CEDAR
IN THE N W QUADRANT, I MAKE
A SECOND BLAZE AND I ADD
SCRIBING "BT".

NOTE: BEARINGS AND DISTANCES
RECORDED ARE MEASURED TO
THE CENTER OF THE BASE OF
THE BT'S.

MAGNETIC DECLINATION 20° E

12-13-76

Larry E. Monrean
LARRY E. MONREAN

MIKE TOMPKINS

OK