

RENEWAL

12-20-76

T 25 S R 2 W

1/4

S 23 | S 24

SEE RENEWALS \* 25 AND \* 59

FOUND

1. B.L.M. BRASS CAP, CAP DISLODGED  
BY UPROOTED ORIGINAL N.E. BEARING  
TREE. CAP IS STAMPED

" " 1/4 "

S 23 | S 24

T 25 S R 2 W

1962

ORIGINAL STONE, I.P. PER REN. 25, NOT FOUND.

2. ORIGINAL 65 NOW A 66 INCH DIAM.  
FIR IS UPROOTED. RECORD BEARING  
N 65° E, 11.2 FEET. TREE HAS WELL  
HEALED BLAZE. ROOT WAD OF TREE  
NOW LIES NORTH OF CORNER POSITION.

#102 ✓

C.S. File No. 59/26 28

CITIZEN NO. 365 B

## FOUND

3. ORIGINAL 30 INCH FIR, NOW A BADLY  
DECAYED STUMP (RECORD) BEARS  
N 37° W, 17<sup>2</sup> FEET. SCRIBING FOUND  
" 1/4 "

BEARING TREES PER RENEWAL # 59.

4. A HEMLOCK 12 NOW A 15 INCH STUMP  
BEARS N S 43° E, 25<sup>2</sup> FEET (REC.  
S 48° E, 26<sup>0</sup> FEET) STUMP SCRIBED  
ON OPEN BLAZE " 1/4 S 24 CS BT "

5. A HEMLOCK 7 NOW A 9 INCH STUMP  
BEARS N 54 1/2° W, 82<sup>2</sup> FEET (REC.  
N 57° W, 83<sup>5</sup> FEET). STUMP SCRIBED  
ON OPEN BLAZE " 1/4 S 23 CS BT "

NO OTHER BEARING TREE FOUND.

## RENEWAL

1. I RESET 1962 B.L.M. MONUMENT  
AT 1/4 CORNER. I ADD " RESET 1976 "  
TO THE CAP.

BEARINGS AND DISTANCES TO FOUND  
BEARING TREES ARE AS LISTED AS IN  
FOUND.

### NEW BEARING TREES

2. SET BRIDGE SPIKE IN A FIR STUMP 64  
INCHES DIAMETER. SPIKE BEARS S  $42\frac{1}{2}^{\circ}$  W,  
32<sup>6</sup> FEET, SPIKE IS STAMPED "B.O. 1".

3. SET BRIDGE SPIKE IN A FIR STUMP 54  
INCHES DIAMETER. SPIKE BEARS S  $18\frac{1}{2}^{\circ}$  E  
16<sup>6</sup> FEET, SPIKE IS STAMPED "B.O. 2".

MAGNETIC DECLINATION  $20^{\circ}$  E

12-20-76

*Larry E. Monrean*  
LARRY E. MONREAN

PETE EARLE

*OK*

C. S. File No. 59/26