

RENEWAL

SEE RENEWAL NO. 144

FOUND

U.S. GENERAL LAND OFFICE SURVEY BRASS

1. CAP AT $\frac{1}{4}$ CORNER, CAP IS STAMPED

" $\frac{1}{4}$ "

S19 | S20

1924

CAP IS ATTACHED TO A 1" x ~~3/8~~" IRON PIPE, AND IS APPROXIMATELY 18 INCHES ABOVE GROUND.

2. ORIGINAL 10" FIR NOW A 23 INCH

DIAM. STUMP BEARS S 64° W, 4² FEET (REC. 4² FEET). I DO NOT OPEN FOR SCRIBING.

NOTE: ORIGINAL SE B.T. IS GONE

3. B.T. PER RENEWAL #144

A R. FIR 13 INCHES DIAM. NOW A

3. DEAD SWAIG 15 INCH DIAM BEARS

N 14 $\frac{1}{2}$ ° W, 34² FEET (REC. N 16° W, 34² FEET)

#215 ✓

C.S. FILE NO. 59/29-A

DIETZEN NO. 385-B

FOUND

TREE DOUBLE BLAZED, SCRIBING
VISIBLE "S 19 CS BT".

RENEWAL

1. AS MONUMENT IS 18 INCHES
ABOVE GROUND AND SLIGHTLY LOOSE,
I REFERRED POSITION OF CAP AND
LOWER IT TO APPROXIMATELY 6 INCHES
ABOVE GROUND AT THE REFERENCED
POSITION.

2. A CEDAR, 18 INCHES DIAMETER BEARS
N $17\frac{1}{2}^{\circ}$ W, 35^E FEET. TREE DOUBLE
BLAZED AND SCRIBED "1/4 S 19 CS BT".

THIS CORNER FALLS NEAR NORTH EDGE OF
CREEK BED (CREEK REROUTED BY BEAVER
DAM) AND ON SOUTH EDGE OF ROAD.

MAGNETIC DECLINATION 20° EAST

1-10-77

OK
[Signature]

[Signature]

K. CHENEY

P. L. EARLE.

NOTE.

THERE ARE NO TREES SUITABLE FOR SCRIBING
IN SECTION 20.

U.S. File No. 59/29-4