

DATE: Feb. 3, 1977

T29S

S28	S27
S33	S34

R1E
1977

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) ORIGINAL CORNER
(6" FIR) (1910)
TREE IS MISSING.

Accessories Found: (Condition and Source) Original 8" Doug. Fir
(Now 17" rotted stump) with visible scribes (R1, S2), BEARS
31^{68'} N 23° E

#136 ✓

RENEWAL

Monument Set: (Procedure and Description) 2 1/2" Brass cap on
3/4" x 1/2" dia. iron pipe set 6" above ground with
surrounding 1 1/2' x 1/2' rock mound.

Stamped: Douglas County Surveyors Office, T295 R1E, 1977

S28 | S27
S33 | S34

New Accessories: (Description) SET THE FOLLOWING B.T.S.

16" Grand fir N 2 3/4° W 39 5' Scribed: T295, R1E, S28^{CS}, BT

9" Yew N 71 3/4° E 44 1' Scribed: T295, R1E, S27^{CS}, BT

19" Doug. Fir S 69 1/2° E 76 0' Scribed: T295, R1E, S34^{CS}, BT

13" Hemlock S 26 1/4° W 148 1' Scribed: T295, R1E, S33^{CS}, BT

Attached county BT tags to all

Location and Comments:

20° E

Compass Declination

U.S. Forest Service

Agency

(Deputy Co. Surveyor)

Gaylord, Dennis

Party Chief

L. Bold, Chuck

Notekeeper

CORNER LIES IN CREEK

Witnesses

BOTTOM, 40' EAST OF

F.S. ROAD No. 2921C

OK [Signature]