

T 20 S R 11 W

DATE: 3-2-77

S 31	S 32
S 6	S 5
T 21 S	

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s ORIGINAL SURVEY, 1891

Monument(s) Found: (Condition and Source) NONE (UNRECORDED STAKE  
OUT OF CORNER POSITION)

ACCESSORIES FOUND: (CONDITION AND SOURCE)

1. ORIGINAL 42 INCH FIR NOW A 46 INCH DIAMETER DECAYED  
STUMP. STUMP HAS WELL HEALED BLAZE WHICH WE OPEN,  
FIND GOOD SCRIBING "T 21 S R 11 W S 6 BT"

2. ORIGINAL 27 INCH FIR NOW A 34 INCH DIAMETER  
TIP OUT (ROOT HOLE WELL DEFINED). TREE HAS WELL  
HEALED BLAZE WHICH WE OPEN, FIND GOOD SCRIBING  
"T 20 S R 11 W S 32 BT" TREE IS DECAYED.

Accessories Found: (~~Condition and Source~~)

3. POSSIBLE ORIGINAL B.T. TO THE S.E. RECORDED  
AS A 36 INCH FIR. FOUND A BADLY DECAYED  
STUMP, NO SCRIBING, APPROXIMATE DIAMETER  
18 INCHES.

N.W. B.T. AN ALDER NOT FOUND.

#90 T21-11 ✓  
#110 T20-11 ✓

SEE RENEWAL FOR BEARING-DISTANCE INFO. Page 1 of 2

C.S. File No. 59/31-1 C

RENEWAL

SET A 1" X 36" IRON PIPE, WITH BRASS CAP ATTACHED, 30 INCHES  
DEEP AT SECTION CORNER, CAP MARKED "DOUGLAS COUNTY  
SURVEYOR T20S R11W  $\frac{531}{56} \frac{532}{35}$  T21S 1977"  
FROM WHICH

RENEWAL

Monument Set: (~~Procedure and Description~~) \_\_\_\_\_

1. 46 INCH FIR STUMP (ACC. FD #1) BEARS S 22° W, 13 <sup>2</sup>/<sub>3</sub>  
FEET TO FACE
2. STUMP HOLE (ACC. FD #2) BEARS N 56 1/2° E, 17 <sup>2</sup>/<sub>3</sub> FEET.
3. 18 INCH STUMP (ACC. FD #3) BEARS S 27° E, 23 <sup>1</sup>/<sub>2</sub> FEET TO  
CENTER (REC. S 29 1/2° E, 23' FEET).

New Accessories: (Description) \_\_\_\_\_

1. A. D. FIR 14 INCHES DIAMETER BEARS S 39° W  
16 <sup>5</sup>/<sub>8</sub> FEET. TREE DOUBLE BLAZED AND SCRIBED  
"T21S R11W 56CS BT".

R \_\_\_\_\_

Location and Comments: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Compass Declination \_\_\_\_\_

Agency \_\_\_\_\_

Party Chief \_\_\_\_\_

Notekeeper \_\_\_\_\_

Witnesses \_\_\_\_\_

DATE: 3-2-77

T 205 R11W

S 31 | S 32

S 6 | S 5

T 215

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #18

Monument(s) Found: ~~(Condition and Source)~~  
NEW ACCESSORIES

2. A D. FIR 14 INCHES DIAMETER BEARS S 62 1/2 ° E  
4<sup>6</sup> FEET. TREE DOUBLE BLAZED AND SCRIBED  
"T 215 R 11 W S 5 CS BT".

3. A W. FIR 9 INCHES DIAMETER BEARS N 34 1/2 ° W  
14<sup>2</sup> FEET. TREE DOUBLE BLAZED AND SCRIBED  
"T 205 R 11 W S 31 CS BT".

NEW  
Accessories Found: ~~(Condition and Source)~~

4. A D. FIR 18 INCHES DIAMETER BEARS N 7 ° E  
25<sup>2</sup> FEET. TREE DOUBLE BLAZED AND SCRIBED  
"T 205 R 11 W S 32 CS BT".

RENEWAL

Monument Set: (Procedure and Description) \_\_\_\_\_

New Accessories: (Description) \_\_\_\_\_

Location and Comments: 20° EAST  
THIS CORNER FALLS D.C.S.O.  
ON THE TOP OF A LARRY E. MONREAN  
RIDGE RUNNING Jerry Monrean  
S 35° W PETE. EARLE  
KAREN CHENEY

Compass Declination  
Agency  
Party Chief  
Notekeeper  
Witnesses

*OK [Signature]*