

U. S. GENERAL LAND OFFICE SURVEY
1/4
51
1937

DATE: MARCH 3, 1977

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) 2 1/2" BRASS
CAP ON 1" IRON PIPE (MARKED AS SHOWN)
BENT OVER & BURIED 1' DEEP. REFERENCE
LOCATION OF PIPE, REMOVE, STRAIGHTEN
& REPLACE IN EXACT SAME LOCATION.
(T30S R1E) TOWNSHIP & RANGE
NOT ON BRASS CAP.

Accessories Found: (Condition and Source) _____

A 32" DOUGLAS FIR BEARS S37°E, 34.98'
HAS A HEALED BLAZE,
B.T. TO SW IS GONE.
PLACED COUNTY B.T. SIGN ON FIR

#37 T30-1E ✓
#143 T29-1E ✓

U. S. File No. 59/31-4

Page 1 of 1

C

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

A 8" YEW BEARS S 65° 30' E,
78.4' SCRIBED "1/4 S I C S BT"
ON A DOUBLE BLAZE. PLACED COUNTY
B. T. ^{SIGN} ON YEW

Location and Comments:	<u>18° E</u>	Compass Declination
CORNER LIES 200' ±	<u>V. S. F. S.</u>	Agency
SOUTH OF F. S.	<u>DENNIS GAYLORD</u>	Party Chief
ROAD # 293	<u>" "</u>	Notekeeper
& 25' ± NORTH	<u>WALTER BARTON</u>	Witnesses
OF THE NORTH	_____	OK <i>[Signature]</i>
BANK (HIGH WATER	_____	
LINE) OF JACKSON		
C RIK.		