

DATE: 4-6-77

T 20 S R 10 W

52	51
511	512

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s SEE 1952 RESURVEY

Monument(s) Found: (Condition and Source) NOT FOUND (SEVERAL TREES ARE DOWN AND HAVE ROLLED OVER THIS AREA).

FOUND A SQUARED WOODEN POST AT SECTION CORNER (NOT OF RECORD)

Accessories Found: (Condition and Source) (TREES PER 1952)

1. AN 8 INCH HEMLOCK NOW A BADLY DECAYED STUMP

BEARS N 31 3/4° E 17⁸ FEET (~~RECORD IN 1952~~)

FACE IS NEARLY ROTTED OUT FRAGMENTARY SCRIBE

MARKS VISIBLE NEAR EDGE OF BLAZE.

#59 ✓

G.S. File No. 59/31-20 Page 1 of 1

C

2. A CEDAR 40 NOW 48 INCHES DIAMETER BEARS S 12 3/4° W 27 1/2 FEET.

TREE MARKED "T 205 R10W S11 BT" ON OPEN BLAZE.

3. A HEMLOCK 8 NOW 9 INCHES DIAMETER BEARS N 33° W 39 1/2 FEET

(REG. N 35 1/4° W 38 1/2 FEET) TREE HAS ~~BEEN~~ PARTIALLY HEALED SINGLE BLAZE.

S.E. 40" FIR IS GONE

RENEWAL

Monument Set: (Procedure and Description) SET BRASS CAP AT SECTION

CORNER MARKED

" DOUGLAS CO. SURVEYOR "

T 205 R10W

22 | S1

S11 | S12

1977

PLACE WOODEN POST ALONG SOUTH EDGE OF CAP.

New Accessories: (Description)

1. A MAPLE 13 INCH DIAMETER BEARS S 44° E 29 1/2 FEET.

TREE DOUBLE BLAZED AND SCRIBED "S12 CS BT"

2. AN ALDER 15 INCH DIAMETER BEARS N 68 1/2° E 25 0 FEET.

TREE DOUBLE BLAZED AND SCRIBED "T 205 R10W S11 CS BT"

Location and Comments:

20° E

D C S O

LARRY E. MONREAN

Larry E. Monrean

ROD KIMBERLING

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]