

T 29 S R 8 W

C 1/4 + S 13

DATE: 5-4-77

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s SHANER 162(MSB-76)1975 & M 39-79A(1970 BOYER)

Monument(s) Found: (Condition and Source) SHANER 1975

IRON PIPE 2 1/4 INCH DIAMETER 8 INCHES HIGH WITH BRASS

CAP ATTACHED MARKED " T 29 S R 8 W W M C 1/4 + S 13 1975 "

THEN S 17° W 49 ± FEET TO BOYER MONUMENT

A 3/4 INCH DIAMETER I. ROD AT C 1/4 AS DETERMINED

BY BOYER PER C.S. FILE M 39-79A.

Accessories Found: (Condition and Source) FROM 1975 (SHANER)

B.C. THE FOLLOWING B.T.'S.

1. A FIR 12 NOW 11 INCH DIAMETER BEARS N 12 1/2° W 18 ±

FEET (REC. N 15° W 17 1/2 FEET). TREE BLAZED WITH SCRIBING

VISIBLE " C 1/4 S 13 BT " .

2. A FIR 12 INCH DIAMETER BEARS S 26 1/2° W 85 ± FEET

(REC. S 25° W). TREE BLAZED WITH SCRIBING VISIBLE

" C 1/4 S 13 BT " .

Page 1 of 1
G.S. File No. 59/34-2

C

B.T.S FROM BOYER MONUMENT.

3. RED FIR 40 NOW 48 INCH DIAM BEARS N 57° E 57² FEET (REC. N 52° 30' E) TREE HAS WELL HEALED BLAZE.

4. RED FIR 10 NOW 13 INCH DIAMETER BEARS S 32° E 19² FEET TO FACE 20² FEET TO CENTER OF BASE.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments:	<u>20° E</u>	Compass Declination
	<u>D C S D</u>	Agency
	<u>LARRY E. MONREAN</u>	Party Chief
	<u><i>Larry Monrean</i></u>	Notekeeper
	<u>R. B. KIMBERLING</u>	Witnesses
	<u>K. CHENEY</u>	
	<u>S. J. FLOUSE</u>	

OK