

DATE: 5-5-77

T 25 S R 1 W

$\frac{1}{4}$ $\frac{S 23}{S 26}$

Condition Report Or
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 106

Monument(s) Found: (Condition and Source) NONE - AREA OF
CORNER LIES ON AREA CAT BLADED FOR FIRE
TRAIL.

Accessories Found: (Condition and Source) _____

1. ORIGINAL 10 INCH FIR NOW DEAD, 15 INCH DIAMETER
 BEARS N 35° W 3 $\frac{3}{4}$ FEET. TREE HAS WELL HEALED
 BLAZE, WE OPEN AND FIND SCRIBING "1/4 S 23".
 GROWTH RINGS INDICATE EXTREMELY SLOW GROWTH.
2. ORIGINAL 18 NOW 22 INCH CEDAR IS DOWN AND
 LODGED AGAINST N W B.T. SCRIBING VISIBLE IN LIPHEMED

#130 ✓

BLAZE "1/4 S BT".
TREES PER RENEWAL # 106

3. A CEDAR 5 INCH DIAMETER BEARING S 12° W 47 1/2 FEET

DISLODGED FOR CAT TRAIL. HAS WELL HEALED BLAZE

4. A D. FIR 8 INCHES DIAMETER BEARING N 73° W 23 1/2 FEET

IS UPROOTED, PARTIALLY BURIED, OPEN BLAZE (UNHEALED) SCRIBING
FOUND "1/4 S 23 CS".

RENEWAL

Monument Set: (Procedure and Description) AT 1/4 CORNER SET

A 1" BY 30" IRON PIPE 26 INCHES IN THE GROUND. BRASS

CAP ATTACHED TO PIPE STAMPED

"DOUGLAS COUNTY SURVEYOR"
T 25 S R 1 W

1/4 S 23
S 26
1977

New Accessories: (Description)

1. SET R.R. SPIKE IN A 36 INCH DIAM. FIR STUMP. SPIKE
BEARS S 50° W 37 1/2 FEET. SPIKE STAMPED "B O".

2. A 12 INCH DIAM. D. FIR BEARS N 54 1/2° W 25 1/2 FEET.
TREE DOUBLE BLAZED AND SCRIBED "1/4 S 23 CS BT".

Location and Comments:
THIS CORNER LIES
ON EW CUTTING
LINE. AREA CLEAR CUT
TO THE SOUTH.

20° E
DCSD
LARRY E. MONREAN
Larry E. Monrean
R. B. KIMBERLING
P. L. EARLE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK 