

T 20 S R 9 W

DATE: 5-10-77

1/4 S7 | S8

Condition Report On  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 1921 SURVEY

Monument(s) Found: (Condition and Source) U.S. GENERAL  
LAND OFFICE SURVEY BRASS CAP RUSTED AND  
OFF AT THE GROUND. CAP MARKED  
BROKEN

" 1/4 "  
 S7 | S8

1921

Accessories Found: (Condition and Source)

1. A D. FIR 40 INCH DIAM BEARS S 57 1/2° E  
 15 FEET. TREE HAS WELL HEALED SINGLE  
 BLAZE - WE DO NOT OPEN.

2. A MAPLE 20 INCH DIAMETER BEARS S 28° W  
 16 FEET. TREE HAS WELL HEALED BLAZE - WE  
 DO NOT OPEN

#28 ✓

C. S. File No. 59/34-12 Page 1 of 1

C

RENEWAL

Monument Set: (Procedure and Description) SET 1" x 30"

DIAM. IRON PIPE AT 1/4 CORNER 26 INCHES  
INTO THE GROUND. ATTACHED BRASS CAP IS  
MARKED

" DOUGLAS COUNTY SURVEYOR "  
T20S R9W

1/4 S 71 58  
1977

New Accessories: (Description)

A MAPLE 33 INCH DIAM. BEARS S 57 1/2° W  
69 3/4 FEET. TREE DOUBLE BLAZED AND  
SCRIBED " 1/4 S 71 58 CS BT "

Location and Comments: 20° EAST Compass Declination

D C S O

Agency

LARRY E. MONREAN

Party Chief

*[Signature]*

Notekeeper

R.B. KIMBERLING

Witnesses

*[Signature]*