

T305 R5W

DATE: 5-25-77

28	27
33	34

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 154, 250, 175, 72

Monument(s) Found: (Condition and Source) DC 50 BRASS CAP.

BLM BRASS CAP AND ~~2" IRON PIPE~~ 0² FT SOUTH AND

A 2" IRON PIPE 0² FT SOUTH

ALL BEARINGS AND DISTANCES ARE FROM THE DC50 B.C.

Accessories Found: (Condition and Source) A 30" B. OAK, NOW 40"

DIAM. BEARS N18°E 16.0 FT (REC 16.7 FT) WITH WELL HEALED

BLAZE. A 13" NOW 21" DIAM. CEDAR BEARS S55°E 54.5 FT

WITH WELL HEALED DOUBLE BLAZE. A 6" NOW 10" MADRONE

(LAUREL) BEARS S81°W 37.0 FT WITH PARTIALLY HEALED T^{DOUBLE}

BLAZE, VISIBLE SCRIBING "305 R5W S33 - BT". A 14" NOW 25"

DIAM. D. FIR BEARS N3°W (REC N1°W) 58.5 FT WITH WELL

(REIN # 72)

Page 1 of 1

U.S. File No. 59/34-24



HEALED BLAZE AND A 3/4" I. PIPE STICKING INTO
BLAZE.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:

<u>20°E</u>	Compass Declination
<u>DCSO</u>	Agency
<u>R. B. KIMBERLING</u>	Party Chief
<u>R. B. Kimberling</u>	Notekeeper
<u>K. CHENEY</u>	Witnesses
<u>P. L. EARLE</u>	

OK
[Signature]