

T29S R7W

DATE: 6-13-77

S 26 1/2	S 26
S 34 1/2	S 35

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 119

Monument(s) Found: (Condition and Source) FD. A Douglas County

BRASS CAP ON A 1" X 30" I. PIPE 10" OUT OF GROUND
AT A 45° ANGLE - (APPARENTLY HAD SLID DOWN HILL)

MARKED "T29S R7W"

S 26 1/2	S 26
S 34 1/2	S 35

1962

FD. A 1" X 27" I. PIPE BURIED ALONG SIDE CAP.

FD. A CONGLOMERATE STONE 6" X 12" X 10" BURIED
24" IN GROUND.

Accessories Found: (Condition and Source) _____

① A 30" D. FIR, NOW 30 IN., BEARS S 31° 45' E,
26¹/₂ FT. (RECORDED AS A 24" TREE 1924)
VISIBLE HEALED BLAZE.

② A 30" D. FIR, NOW 28 IN., BEARS N. 15° E.,
(REC. N. 12° 45' E.), 29¹/₂ FT. (RECORDED AS A
20" TREE IN 1924 RESURVEY) VISIBLE HEALED
double blaze.

#243 ✓

RENEWAL

Monument Set: (Procedure and Description) (STAMPED "RESET 1977")

- ① REPLACE Douglas County BRASS CAP IN PROPER POSITION.
- ② A CONGLOMERATE STONE, 6" X 12" X 10" BURIED 24" UNDER GROUND ON EAST SIDE OF E.C.
- ③ A 1" X 27" I. PIPE ON NE SIDE OF CAP

New Accessories: (Description)

NO OTHER TREES AVAILABLE

Location and Comments:

<u>20° EAST</u>	Compass Declination
<u>D.C.S.O</u>	Agency
<u>R.B. KIMBERLING</u>	Party Chief
<u>Karen Clancy</u>	Notekeeper
<u>ST FLAISE</u>	Witnesses

OK
[Signature]