

T295

R	524		519	R
6		+		5
W	525		530	W

DATE: 6/14/77

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #162 (T29-5) #204 (T29-6)

Monument(s) Found: (Condition and Source) BRASS CAP BEARS

N68°E 17¹/₄ FT. DIST. FROM ORIG. CORNER LOCATED FROM
O.B.T. DESCRIBED BELOW. BC STAMPED-

COUNTY		SURVEYOR'S	OFFICE	
R	T295		R	
6	524 519		5	
W	525 530		W	
1969				

Accessories Found: (Condition and Source) FROM BRASS CAP

A 13 INS., NOW 18 INS. DIAM. D. FIR BEARS S40°W 25¹/₄ FT. DIST.

A 14 INS., NOW 22 INS. DIAM. D. FIR BEARS N43°W 30²/₃ FT. DIST.

A 6 INS., NOW 8 INS. DIAM. D. FIR BEARS S56°E 35²/₃ FT. DIST.

(REC. 25²/₃ FT.) BEARING TREE TAG SAID 35²/₃ FT. ALL BT'S
HAD DOUBLE WELL HEALED BLAZES. FROM APPARANT^E ORIG.
CORNER LOCATION A D. FIR STUMP, 15 INS. NOW 40 INS. DIAM.

#184 T29-5 ✓
 #233 T29-6 ✓

Page 1 of 1
 C.S. File No. 59/34-38 C

BEARS 52°E 137³ FT. DIST. WITH PREV. OPENED SINGLE
BLAZE. FOUND SCRIBING " 2 "
230
BT

RENEWAL

Monument Set: (Procedure and Description) RESET BRASS CAP IN
~~ASSUMED~~ ORIG. LOCATION, STAMPED TO NOW READ

COUNTY	SURVEYOR'S		OFFICE
R	T295		R
6	S24	S19	5
W	S25	S30	W

RESET
1977

New Accessories: (Description) DROVE A 5/8" IRON 1969

ROD WITH ALUM. CAP AT LOCATION WHERE WE REMOVED
BRASS CAP. ALUM. CAP BEARS N68°E 17⁴ FT. DIST., STAMPED
"CS 1977". WE USED ALREADY SCRIBED BT'S WHICH NOW FACE
5/8" I.R., AS FOLLOWS; A 18 INS. DIAM. D. FIR BEARS S0°30'W

13⁷ FT. DIST. A 22 INS. DIAM. D. FIR BEARS N9°W 28⁴ FT. DIST.
A 8 INS. DIAM. TWIN TRUNKED D. FIR BEARS S75°E 47⁹ FT DIST. ALL
BT'S HAVE DOUBLE WELL HEALED BLAZE

Location and Comments:	<u>20°E</u>	Compass Declination
A WIRE FENCE RUNNING	<u>DC 50</u>	Agency
W. & N HAS CORNER	<u>R. KIMBERLING</u>	Party Chief
WHICH BEARS N15°E	<u>R B Kimberling</u>	Notekeeper
350 FT DIST.	<u>P. EARLE</u>	Witnesses

OK 