

T 20 S

1/4 533

54

T 21 S

R
=
W

DATE: 6-15-77

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 55(T21-11) #59(T20-11)

Monument(s) Found: (Condition and Source) A 1 INCH DIAMETER
IRON PIPE AT 1/4 CORNER AS PROPORTIONED
BY STUNTZNER PER RENEWAL NUMBER
55.

Accessories Found: (Condition and Source) _____

1. A D. FIR 32 INCHES DIAMETER BEARS N 50° W 18 FEET.

TREE BARK SCRIBED " S 33 1/4 "

2. A D. FIR 42 NOW 52 INCHES DIAMETER BEARS

N 82° E 95 FEET. TREE HAS UNHEALED BLAZE

SCRIBED " S 33 1/4 "

#112 T20-11 ✓
 #93 T21-11 ✓

RENEWAL

Monument Set: (Procedure and Description) SET A 1' X 30" IRON PIPE WITH

BRASS CAP ATTACHED AT 1/4 CORNER AS DETERMINED BY STUNTNER, CAP STAMPED

" DOUGLAS CO. SURVEYOR "

T 205

1/4 533 R 11W

T 215

1977

SET 1" I. PIPE ALONG EASTERLY EDGE OF CAP.

New Accessories: (Description)

A D. FIR 48 INCHES DIAMETER BEARS S 4 1/2° W

88 4 FEET, TREE DOUBLE BLAZED AND SCRIBED "1/4 S4 CS BT",

Location and Comments:

CORNER LIES AT NE
CORNER OF STAND
OF TIMBER.

20° EAST

DCSD

LARRY E. MONREAN

Larry L. Monrean

KAREN CHENEY

STEVE J. FLAUSE

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]