

MARKS ON
BED ROCK

DATE: 7-5-77

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

+ III



(T255, RIW $\frac{28}{33} | \frac{27}{34}$)

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) see sketch
above of marks on bed rock.

Accessories Found: (Condition and Source) _____

A 17" FIR SNAG BEARS N74°E,
SCRIBING VISIBLE ON PARTLY ~~HEALED~~ ^{BURNED} BLAZE,

"T2-S R--S2-BT"

A ROCK POINT BEARS S65°W, 19.1'
(Roc. 25.7') NO MARKS VISIBLE.

BEARING TREES TO THE NW & SE
ARE GONE.

#131 ✓

C. S. File No. 59/38-1



New Accessories

A Point of Rock bears $S65\frac{1}{2}^{\circ}W, 204'$
MARKED "X BO" -

RENEWAL

Monument Set: (Procedure and Description)

I CHISELED THE EXISTING MARKS
ON THE BED ROCK SO THEY
SHOW BETTER.

New Accessories: (Description) A 12" DOUG FIR BEAMS
 $S87^{\circ}E, 90.0'$ SCRIBED "T255 R1W534 CSBT"
ON A DOUBLE BLAZE. A 16" DOUG FIR BEAMS
 $N36^{\circ}E, 24.3'$ SCRIBED "T255 R1W527CSBT"
ON A DOUBLE BLAZE. A 11" DOUG FIR BEAMS
 $N29^{\circ}30'W37.1'$ SCRIBED "T255 R1W528CSBT"
ON A DOUBLE BLAZE. PLACED B.T. SIGNS ON ALL.

Location and Comments:	<u>19°E</u>	Compass Declination
CORNER LIES APPROX.	<u>U.S. F.S.</u>	Agency
1000' SOUTH OF	<u>D. GAYLORD</u>	Party Chief
END OF NEW	<u>" "</u>	Notekeeper
U.S. PLYWOOD ROAD,	<u>TRAVIS WORTHEN</u>	Witnesses

OK
JHL