

T245

1/4 COR

534/535

RIW

1977

DATE: 7-25-75

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s NONE

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) A FIR, 36 INS. NOW
40 INS. DIAM., BEARS S78°E 9⁹ FT. WITH WELL HEALED
DOUBLE BLAZE. A FIR, 10 INS. NOW 19 INS. DIAM., BEARS
N53°W 23⁸ FT. WITH WELL HEALED DOUBLE BLAZE. WE
OPENED UPPER BLAZE AND FOUND SCRIBE MARK
"S"

#125 ✓

C. S. File No. 59/38-6 Page 1 of 1

C

RENEWAL

Monument Set: (Procedure and Description) SET 1" X 36" IRON PIPE

WITH BRASS CAP 6 INS. ABOVE GROUND MARKED

COUNTY SURVEYORS OFFICE
T245
V4/COR
534 | 535
RIW
1977

New Accessories: (Description) NONE

Location and Comments:

CORNER IS AT
N.E. COR. OF
CLEARCUT UNIT.

20° E
DCSD
R.B. KIMBERLING
R.B. Kimberling
P.L. EARLE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]