

T285

DATE: 7-28-77

R
3
W

—
54
T295

1/4 COR
4 ONLY

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) A 2" x 2" x 34" CUT (SQUARED)
STAKE WITH FLAGGING, STUCK LOOSELY IN GROUND

Accessories Found: (Condition and Source) A 12 INS. DIAM. MAPLE
BEARS S80°E 39 1/2 FT, APPEARS TOO SMALL TO HAVE BEEN
6 INS. DIAM. IN 1910. ORIG. WEST FACE SPLIT OFF, NO EVIDENCE
OF ORIG. BLAZE, ~~NO~~ VISABLE SCRIBING IN ~~THE~~ BLAZE (ABOVE
SPLIT-OFF FACE). A 17 INS. DIAM. MAPLE BEARS EAST
60 ± FT. OF 12 INS. MAPLE. EAST SIDE SPLIT OUT AND
CENTER ROTTED AWAY. HEALED SCAR INDICATES

~~##~~ NF ✓

C. S. File No. 59/38-9

POSSIBLE
~~PROBABLE~~ BLAZE FACING N 80°W, BUT NO EVIDENCE
OF SCRIBING. ~~FEET~~. (FROM STAKE) A 20 INS. NOW 24 INS.
D. FIR BEARS N 67½°E 46² FT. WITH WELL HEALED
BLAZE.

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:

20°E

DC 50

R. B. KIMBERLING

R. B. Kimberling

P. L. EARLE

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]