

T 245

DATE: 8-11-77

R	535	536
I		
W	52	51

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

T 255

Previous Renewal #'s 35 IN T245 & # 53 IN T255 (DCSO 1963 REN)

Monument(s) Found: (Condition and Source) DCSO BRASS CAP

IRON PIPE SEPARATED AND BADLY BENT, BELOW SURFACE

OF CAT TRAIL, CAP IS STAMPED

COUNTY SURVEYORS OFFICE "

T 245

R	535	536
I		
W	52	51

T 255

1963

Accessories Found: (Condition and Source) ORIGINAL

1. A FIR 16 NOW A 26 INCH DIAMETER SNAG BEARS N 14° E

15⁸ FEET. TREE HAS WELL HEALED BLAZE.

2. A FIR 10 INCH DIAMETER NOW DEAD BEARS S 30° E 13² FEET

(ORIGINAL REC S 10° E 1963 RENEWAL REC. S 30° E). TREE

HAS PARTIALLY OPENED BLAZE SCRIBED "T 255 PI W 51"

3. A 48 INCH DIAMETER PINE STUMP BEARS S 15° W

13⁹ FEET. TREE HAS WELL HEALED BLAZE.

#126 T24-1 ✓

#132 T25-1 ✓

U.S. FILE NO. 59/38-14

Page 1 of 1

C

4. A FIR 10 NOW 16 INCH DIAMETER BEARS N 26° W 20 1/2 FEET.
TREE HAS WELL HEALED BLAZE
B.T.'S PER 1963 RENEWAL

5. A 21 INCH DIAMETER FIR STUMP BEARS S 55° W 11 1/2 FEET.

TREE HAS PARTIALLY HEALED BLAZE SCRIBED "255 RIW 52 CS" VISIBLE.

6. AN INCENSE CEDAR 12 INCHES DIAMETER BEARS N 47° E 24 1/2 FEET.

TREE HAS OPEN BLAZE SCRIBED "T245 RIW 536 CS BT".

RENEWAL

Monument Set: (Procedure and Description) SET 30 BY 1 INCH

IRON PIPE AT SECTION CORNER 22 INCHES DEEP ATTACHED

" DOUGLAS COUNTY SURVEYOR "

BRASS CAP IS STAMPED.

T 245

R 535 / 536
W 52 / 51

T 255

New Accessories: (Description) NO TREES TO SCRIBE

IN SOUTHERLY QUADRANTS.

Location and Comments:

20° E

Compass Declination

DCSO

Agency

LARRY E. MONREAN

Party Chief

Larry E. Monrean

Notekeeper

MIKE CLINE

Witnesses

OK
[Signature]