

T 325 R 7W

DATE: 8-22-77

28	27
33	34

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 1, ALSO CS 59/30 (REF. OUT NOTES)

Monument(s) Found: (Condition and Source) NO TRACE OF

ORIGINAL POST OR 2" I PIPE SET BY LARSEN, (REN.#1) IN 1954.

Accessories Found: (Condition and Source) NO TRACE OF ORIGINAL

FOUND

BEARING TREES. FROM REN.#1, A 30" FIR NOW A 32" D. FIR

STUMP, WITH SCRIBING "BT" AND OTHER ILLEGIBLE SCRIBING VISIBLE

ON AN UNHEALED DOUBLE BLAZE. THIS CORNER WAS REFERENCED

OUT FOR ROAD CONSTRUCTION IN 1972 BY J.M. POWELL, DOUGLAS CO.

SURVEYOR'S OFFICE, (SEE CS ~~38~~ 59/30). FOUND "PK" NAIL IN

ABOVE MENTIONED STUMP AND $\frac{3}{8}$ " I ROD, FIRMLY SET, 10³ FT. N 42° W

OF THE BT STUMP. WE ESTABLISH THE CORNER AT N 42° W Page of

106^B FT., FROM THE FOUND $\frac{5}{8}$ " I. ROD.

C.S. FILE No. 59/38-19 C

WE FIND THE FOLLOWING BT'S AS NOTED IN REV. # 1.

A 32" D. FIR STUMP, PREVIOUSLY DESCRIBED, BEARS S 42° E 117 1/2 FT.

A 6" TANOAK, NOW AN 8" SNAG, WITH SCRIBING "3642 BT" VISIBLE ON UNHEALED BLAZE BEARS S 54 1/2° W 120 2 FT. (REC. S 54 1/2° W 119 6 FT.)

AND A 5" NOW 10" TANOAK, WITH SCRIBING "3642 BT" VISIBLE ON UNHEALED BLAZE BEARS N 42° W 87 FT. (REC. N 42° W 86 1 FT.)

RENEWAL

Monument Set: (Procedure and Description) AT THE CORNER POINT, WE

SET A 1" X 30" I. PIPE, 20" IN THE GROUND WITH MOUND OF STONE TO TOP,

WITH BRASS CAP ATTACHED, MARKED: DOUGLAS COUNTY SURVEYOR

T 325 R 7W

528 | 527

533 | 534

1977

new Accessories: (Description)

A 16" D. FIR, SCRIBED "T 325 R 7W 533 CS BT" ON A DOUBLE BLAZE BEARS S 44° W 97 8 FT.

AND AN 18" LIVE OAK, SCRIBED "T 325 R 7W 534 CS BT" ON A DOUBLE BLAZE, BEARS S 81° E 76 6 FT.

Location and Comments:

20° EAST

Compass Declination

CORNER LOCATED 31 FT.

DOUGLAS COUNTY SURVEYOR

Agency

WEST OF THE CENTERLINE

GARY L. LANGLITZ

Party Chief

OF COW CREEK ACCESS

Gary L. Langlitz

Notekeeper

ROAD AND ONE FOOT

M. W. CLINE

Witnesses

EAST OF A STEEL FENCE

POST WITH SURVEY

MARLER WITNESS SIGN

ATTACHED.

OK
[Signature]

Reference

28 | 27
33 | 39

T32S R7W

Found T. P. H. & Bearing Trees

Renewal #1 -

S.W. & N.W. Bearing Trees

Will be ok.

30" Fir S42E 117.1 Drove

PK Nail for sight. Set 5/8" Rod

S42E 106.8

NE BT Will Be destroyed -

New cor will fall in New Rd -

about next June -

Location approx. 400 ft SE

of Cook Creek

5-9-72

J. J. O.

C.S. File No. 59/38-19

REF.
NOTED -
24