

DATE: 8-30-77

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

+
 1/4 S S
 SC
 T285 R8W

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) 2" IRON PIPE, LOOSLEY SET,
EXTENDING 15" ABOVE GROUND, WITH BRASS CAP ATTACHED, MARKED AS
DESCRIBED IN THE OFFICIAL RECORD OF THE 1961 RESURVEY.

THIS CORNER IS LOCATED IN A LOGGED AREA. WE FIND DISCREPANCIES
IN THE MEASUREMENTS TO THE CORNER ACCESSORIES FROM THE PRESENT
POSITION OF THE MONUMENT. ALSO, WE DO NOT FIND THE MOUND
OF STONE PUT IN PLACE IN 1961. BLM APPROX. CORNER POINT #404,
A 2" I. PIPE WAS NOT FOUND. WE THEREFORE CONCLUDE THAT THIS MONUMENT
HAS BEEN DISTURBED AND PROCEED TO RESET IT AT THE POSITION AS
INDICATED IN THE OFFICIAL RECORD.

Accessories Found: (Condition and Source) _____

PROBABLE REMAINS OF THE SE BEARING TREE, NOW A SHATTERED
HEMLOCK STUMP, SIZE INDETERMINATE, BEARS S 10° E 20³ FT., NO
MARKINGS FOUND.

A 24" HEMLOCK STUMP, WITH WELL-HEALED BLAZE, BEARS
S 65° E 37⁶ FT.

#163 ✓

AND A 46" RED CEDAR STUMP, WITH SCRIBING "1/4 SS SC BT" VISIBLE
ON PARTIALLY HEALED BLAZE, BEARS S 83° W 12 5/8 FT..

RENEWAL

Monument Set: (Procedure and Description) AT THE CORNER POINT WE
RESET ^{THE} 2 1/2" x 28" I. ~~ROD~~ PIPE, 24" IN THE GROUND ON A STEEP
NORTH SLOPE, WITH BRASS CAP MARKED AS DESCRIBED IN THE
OFFICIAL RECORD. WE ADD THE MARKINGS "RESET 1977"

New Accessories: (Description) NONE

Location and Comments:

SET FENCE POST WITH
SURVER MARKER WITNESS
SIGN ATTACHED ONE
FOOT EAST OF THE
CORNER.

20° EAST
DOUGLAS Co. SURVEYOR
GARY L. LANGLITZ
Gary L. Langlitz
STEPHEN J. FLAUSE
JEAN HOLDER
VICKI WOODRAL

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
JH