

T255 R2W

DATE: 8-31-77

$\frac{1}{4} \frac{9}{16}$

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 77

Monument(s) Found: (Condition and Source) B.L.M. BRASS CAP

MARKED " $\frac{1}{4} \frac{59}{516}$ " ON A 2 IN. DIAM. IRON PIPE BURIED
 T255 R2W
 1962 → UNDER A 34 IN. DIAM. D. FIR LOG.

(AT A 45° ANGLE) A ^{STONE} ~~ROCK~~, 14" x 12" x 4" NOW 14" x 9" x 4" (BROKEN
 IN RESETTING) AT THE SOUTH SIDE OF BRASS CAP WITH
 " $\frac{1}{4}$ " CHISELED ON NORTH FACE. OTHER STONES FOUND
 AROUND IRON PIPE.

Accessories Found: (Condition and Source) A ²⁰ ~~32~~ IN. NOW 34 IN. DIAM.
 D. FIR, UPROOTED AND LAYING ACROSS BRASS CAP. BLAZE
 APPARENTLY ON GROUND SIDE. ^{CENTER OF} "ROOT HOLE" ^{BEARS} APPROX. N27°E
^{2^b} FT. AN 8 IN. HEMLOCK SNAG BEARS S6 1/2°E 96² FT (REC.
^{95⁵} FT.), BLAZED AND MARKED " $\frac{1}{4} 516$ C.S. BT".

#105 ✓

RENEWAL

Monument Set: (Procedure and Description) CUT AWAY SECTION OF
LOG AND STRAIGHTENED IRON PIPE WITH BRASS CAP
AT GROUND LEVEL
STAMPED "RESET 1977" ABOVE 1962. RESET CHISELED
STONE ^{AT} ~~ON~~ NORTH SIDE OF BRASS CAP.

New Accessories: (Description) A 6" DIA. D. FIR BEARS N54°W
44⁴ FT., DOUBLE BLAZED AND MARKED "V4S9T255 R2W
CS BT". A 5" DIA. D. FIR BEARS S22°E 14⁶ FT. DOUBLE
BLAZED AND MARKED "V4S16T255 R2WCS BT". SET A
BOAT SPIKE ON ROOT WAD DIRECTLY ABOVE BRASS CAP,
STAMPED "B.O. NO. 1"

Location and Comments:	<u>20°E</u>	Compass Declination
	<u>DCSO</u>	Agency
	<u>R. B. KIMBERLING</u>	Party Chief
	<u>R. B. Kimberling</u>	Notekeeper
	<u>P. L. EARLE</u>	Witnesses
	<u>M. W. CLINE</u>	

OK