

DATE: 8-31-77

T 27 1/2 S R B W

1/4 S 32

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) A 2 1/2" X 28" IRON PIPE

WITH BLM CADASTRAL SURVEY BRASS CAP MARKED

" T 27 1/2 S R B W "

1/4 S 32

1961

CADASTRAL SURVEY

CAP IS 24 INCHES ABOVE GROUND / LEAVING BEARINGS

AND DISTANCES TO BEARING TREES INDICATE THAT

CAP IS NOT IN ORIGINAL POSITION.

Accessories Found: (Condition and Source) _____

1. A HEMLOCK 18 INCH NOW A 22 INCH DIAMETER

STUMP BEARS N 61° E 68° FEET. SCRIBING

" S 32 BT " VISIBLE ON REMAINING PARTIALLY

HEALED BLAZE.

2. A CEDAR 20 NOW A 19 INCH DIAMETER

STUMP BEARS N 69° W 16⁵ FEET. #

#10 ✓

SCRIBING "1/4 332 BT" VISIBLE ON

PARTIALLY HEALED BLAZE.

RENEWAL

Monument Set: (Procedure and Description) WE REPLACED

MONUMENT (PREVIOUSLY DESCRIBED) AT 1/4 CORNER POSITION

AS REFERENCED FROM BEARING TREES. MONUMENT

SET 16 INCHES DEEP AND ADDED MARKS

"RESET 1977" TO BRASS CAP, MOUND STONE
AROUND MONUMENT.

New Accessories: (Description) _____

Location and Comments:

CORNER IS ON
STEEP EASTERLY
SLOPE IN LOGGED
OFF AREA.

20° EAST

DCSO

GARY LANGLITZ

Larry L. Monrean

LARRY E. MONREAN

STEVE J. FLAUS

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

OK
[Signature]