



DATE: 9-7-77

- Condition Report On
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) NONE

Accessories Found: (Condition and Source) ORIGINAL 12", NOMN

26", WHITE FIR BEARS S 35° W, 13.2'
HAS A HEALED BLAZE. BEARING TREE
TO THE NW IS GONE.

#4 ✓

c

RENEWAL

Monument Set: (Procedure and Description) REFERING TO
ONLY ORIGINAL B.T. REMAINING, I
SET A 2 1/2" BRASS CAP ON A 1" IRON
PIPE, STAMPED AS SHOWN ON REVERSE.

New Accessories: (Description) A 27" DOUGLAS FIR
BEARS N 17° E, 18.4' SCRIBED
" 1/4 S 30 C S BT" ON A DOUBLE
BLAZE. PLACED COUNTY B.T. SIGNS
ON BOTH ORIGINAL & NEW B.T.S

Location and Comments:	<u>20° EAST</u>	Compass Declination
<u>CORNER LIES</u>	<u>U.S.F.S.</u>	Agency
<u>APPROX. 300'</u>	<u>DENNIS GAYLORD</u>	Party Chief
<u>NORTH OF</u>	<u>" "</u>	Notekeeper
<u>DIAMOND LAKE.</u>	<u>TRAVIS WORTHEN</u>	Witnesses

OK
[Signature]

T275 R6E

DATE: Aug 9, 1979

$\frac{1}{4}$ $\frac{530}{531}$

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 4

Monument(s) Found: (Condition and Source) I questioned the validity of the tree which I assumed to be the original B.T. when I renewed this corner on 9/7/77, so I opened the blaze with a chain saw & found that there was no scribing on the face, thus this tree is not an original B.T.

Accessories Found: (Condition and Source) I removed the brass capped monument and destroyed (obliterated) the scribing on the new Bearing tree & marked on 9/7/77. I then used a staff compass & steel chain & chained from the corner

30/29
31/32

, 1/2 mile west & made an
extensive search for original evidence,
but found none.

RENEWAL

Monument Set: (Procedure and Description) _____

New Accessories: (Description) _____

Location and Comments: _____

Dennis L. Hayward
Compass Declination
Agency
Property of
Notekeeper
Witnesses