



DATE: 9-9-77

Condition Report On
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s #15 RIW

Monument(s) Found: (Condition and Source) BRASS CAP

HAS BEEN TORN OUT OF THE GROUND. (BRASS CAP STAMPED AS SHOWN ABOVE.) WHILE DIGGING TO RE-SET BRASS CAP, THE ORIGINAL CORNER^{STONE} WAS FOUND BURIED UPSIDE DOWN, MARKED "1/4".

Accessories Found: (Condition and Source) ORIGINAL^{36", Now} 31"

(DBH on HIGH SIDE) DOUGLAS FIR BEARS ~~S10°~~ S15°W, 10.6', HAS A HEALED BLAZE & B.L.M. B.T. SIGN.

23" DOUGLAS FIR SET IN 1965 BEARS S82°E (TO BASE OF TREE WHICH IS LEANING SLIGHTLY DOWNHILL) 24.6'

#128 T24-1W

PARTLY HEALED BLAZE WITH SCRIBING
VISIBLE, " 5198", ALSO HAS B.L.M.
B.T. SIGN. PLACED COUNTY B.T.
SIGNS ON BOTH. THE ORIGINAL
N.E. B.T. IS DOWN.

RENEWAL

Monument Set: (Procedure and Description) ^{BOTH} USING THE
ORIGINAL AND THE 1965 BEARING TREES
FOR REFERENCE, I RE-SET THE 1965
BRASS CAP & STAMP IT "1977"

New Accessories: (Description) NONE

Location and Comments:	<u>22° E</u>	Compass Declination
PLEASE SEND A COMPLEMENTARY COPY OF THIS RENEWAL TO THE LANE COUNTY SURVEYOR	<u>U.S. F.S.</u>	Agency
	<u>DENNIS GAYLORD</u>	Party Chief
	<u>" "</u>	Notekeeper
	<u>TRAVIS WORTHEN</u>	Witnesses

OK
