



DATE: 9-12-77

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s _____

Monument(s) Found: (Condition and Source) 2 1/2" BRASS

CAP STAMPED AS SHOWN ABOVE, ^{PIPE} IS

BENT 90° & BURIED. REMOVED &

STRAIGHTENED PIPE, THEN RE-SET
IN EXACT SAME LOCATION.

TOWNSHIP & RANGE NOT ON B.C.
(T25S, R2E, W.1M.)

Accessories Found: (Condition and Source) ORIGINAL

~~#~~ 14" DOUGLAS FIR BEARS N31°W, 7.92', IS
ALIVE & WELL - HAS A HEALED BLAZE.

ORIGINAL 24", Now 31", DOUGLAS FIR
BEARS S66°E, 31.02', IS ALIVE & WELL.

HAS A HEALED BLAZE. PLACED ~~IN~~ COUNTY
BEARING TREE SIGNS ON BOTH.

#1 ✓

C. S. File No. 59/40 - 8 Page 1 of 1
C

RENEWAL

Monument Set: (Procedure and Description) REPLACED

BRASS CAP IN EXACT ORIGINAL
POSITION.

New Accessories: (Description) NONE

Location and Comments:

LIES IN A PARTIAL
CUT UNIT, 800'
~~SE~~ OF F.S.
ROAD # 2553.

11° E
U.S. F.S.
DENNIS GAYLORD
" "
TRAVIS WORTHEN

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]