

DATE: 9-13-77

TZ15 R10W

9	10
16	15

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewal #'s 1919 RESURVEY, MAP FILE M 62-78

Monument(s) Found: (Condition and Source) ORIGINAL STONE, A SANDSTONE,  
FIRMLY SET, EXTENDING 10" ABOVE GROUND, WITH 4 NOTCHES ON THE SOUTH EDGE,  
AND 3 NOTCHES ON THE EAST EDGE. ALSO FOUND BADLY RUSTED 2" I. PIPE,  
LOOSELY SET, EXTENDING 16" ABOVE GROUND, WITH BRASS CAP ATTACHED, MARKED:

U.S. GENERAL LAND OFFICE SURVEY

TZ15 R10W

S9	S10
S16	S15

NOTE: OFFICIAL RECORD HAS BRASS CAP DATED 1919.

1918

Accessories Found: (Condition and Source) THE ONLY REMAINING ORIGINAL

BT, AN ORIG 12" NOW 38" HEMLOCK, WITH ILLEGIBLE 1919 RESURVEY MARKS

VISIBLE ON PARTIALLY-HEALED BLAZE WHICH FACES APPROX. N 30° W,

BEARS S 73° E 12<sup>5</sup> FT., (REC. ORIGINAL SURVEY S 33° E 12<sup>5</sup> FT.)

AND (REC. 1919 RESURVEY S 73° E 12<sup>5</sup> FT.)

FROM 1919 RESURVEY, A ROTTING ALDER ROOT SHELL BEARS N 68° E 52<sup>0</sup> FT.

#47 ✓

THE SW BT IS GONE

AND A 24" NOW 38" HEMLOCK, WITH ILLIGIBLE SCRIBE MARKS VISIBLE  
ON A PARTIALLY-HEALED BLAZE BEARS N 23° W 23<sup>8</sup> FT.

RENEWAL

Monument Set: (Procedure and Description) AT THE LOCATION OF THE  
FOUND CORNER STONE, WE SET A 1" x 30" T. PIPE, 26" IN THE  
GROUND, WITH BRASS CAP ATTACHED, MARKED; DOUGLAS COUNTY SURVEYOR

T 21 S

59 | 510

516 | 515

R 10 W

1977

WE PLACE THE OLD BRASS CAP AND ORIGINAL  
STONE ALONGSIDE THE NEW BRASS CAP.

New Accessories: (Description)

WE MARK:

A 12" HEMLOCK, DOUBLE BLAZED AND SCRIBED "T 21 S R 10 W 516 CSBT"  
BEARS S 18° W 19<sup>4</sup> FT.

Location and Comments:

20° EAST

Compass Declination

DOUGLAS CO. SURVEYOR

Agency

GARY L. LANGLITZ

Party Chief

Gary L. Langlitz

Notekeeper

STEPHEN J. FLAISE

Witnesses

#47

OK  
*[Signature]*

C.S. 59/40