

T255 R5W

DATE: 10-18-77

20 / 21
1/4

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewal #'s 13, 24

Monument(s) Found: (Condition and Source) NO TRACE OF ORIGINAL
CORNER POST OR 1 1/2" I. PIPE (REN. #13) OR 2" STEEL SHAFT,
(REN. #24). NOTE: CONSIDERABLE CONSTRUCTION ACTIVITY HAS
TAKEN PLACE IN THIS AREA.

Accessories Found: (Condition and Source) FB: THE ONLY REMAINING
ORIGINAL BT, AN ORIG 12" NOW 45" FORKED B. OAK, DIAMETER MEASURED
BELOW THE FORK, ALIVE WITH WELL HEALED ORIGINAL AND
RESCRIBIBLE BLAZES.

FROM REN. #24, AN 18" NOW 18" W. OAK, ALIVE WITH WELL HEALED
SINGLE BLAZE.

#136 ✓

G. S. File No. 5940-48

Page 1 of 1

6

RENEWAL

Monument Set: (Procedure and Description) AT THE CORNER POINT AS
DETERMINED BY COLE IN 1920 (REN. #13) AND ELNER IN 1947 (REN. #24), WE SET
A 1" X 30" I. PIPE, BURIED 4" BELOW GROUND SURFACE, WITH BRASS CAP
ATTACHED, MARKED: DOUGLAS COUNTY SURVEYOR

520 | 521

1/4

New Accessories: (Description)
RSW
1977

AN ORIGINAL BT, A 45" B. OAK, PREVIOUSLY DESCRIBED, BEARS S 49³/₄° E 42¹/₂ FT.
(REC. S 49° E 42³/₄ FT.)

AND AN 18" W. OAK, PREVIOUSLY DESCRIBED, BEARS S 42^W° 139° FT. (REC. PER
REN. #24, S 41° 43' W 137⁹⁴/₃ FT.)

Location and Comments:
CORNER LOCATED IN
LEVEL, GRAVELLED PARKING
AREA, APPROX. 175 FT EAST
OF A HOUSE AND APPROX.
13 FT. WEST OF A WHITE-
PAINTED BOARD FENCE.

20° EAST
DOUGLAS CO. SURVEYOR'S OFFICE
GARY L. LANGLITZ
Gary L. Langlitz
LARRY E. MONREAN
STEPHEN J. FLAUSE

Compass Declination
Agency
Party Chief
Notekeeper
Witnesses

OK
[Signature]