



DATE: 10-20-77

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s \_\_\_\_\_

Monument(s) Found: (Condition and Source) NONE

(ORIGINAL 14")

Accessories Found: (Condition and Source) A 18" DOUGLAS

FIR STUMP BEARS N41°E, 42.9' STUMP  
IS NEARLY COVERED BY DIRT. AFTER  
CONSIDERABLE DIGGING, I OPEN A  
SMALL PORTION OF THE HEALED BLAZE  
& FIND SCRIBING & REVERSE SCRIBING.  
THE BEARING TREES TO THE NW, SW,

#156 ✓

Page 1 of 1  
G.S. Form No. 59/90-51 c

AND TO THE SE ARE ALL  
GONE. (EXTENSIVE LOGGING IN THE  
VICINITY)

RENEWAL

Monument Set: (Procedure and Description) SET 1 1/2"  
GALV. IRON PIPE WITH 2 1/2" BRASS CAP  
STAMPED AS SHOWN ON REVERSE. I  
PLACE A STONE MOUND AROUND  
THE PIPE 2' x 2' x 1' HIGH.

SET BY REFERENCE TO ONLY REMAINING ORIGINAL  
BEARING TREE.  
New Accessories: (Description) A 6" GRAND FIR

BEARS N64°E, 12.9' SCRIBED "T30S RIW  
S3 CSBT" ON A DOUBLE BLAZE.

A 6" GRAND FIR BEARS N67°30'W, 25.0'  
SCRIBED "T30S RIW S4 CSBT" ON A  
DOUBLE BLAZE. PLACED COUNTY B.T. SIGNS  
ON BOTH TREES.

Location and Comments:

CORNER LIES  
500' SOUTH

OF F.S. ROAD No. 2929

THE CORNER <sup>ONLY</sup> 59/510  
C.C.

BEARS N87°E, 167.2'

(RECORD EAST, 165.0')

20°E

U.S. F.S.

DENNIS GAYLORD

" "

ROLLAND SIMSHAUSER

Compass Declination

Agency

Party Chief

Notekeeper

Witnesses

*OK ghl*