

COUNTY SURVEYORS  
T30S R1W  
53  
59 | 510  
C.C.  
1969  
OFFICE

DATE: 10-20-77

Condition Report Only  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In  
 Referenced Out

Previous Renewal #'s 120

Monument(s) Found: (Condition and Source) 2 1/2" BRASS CAP  
ON A 1" IRON PIPE. BRASS CAP, STAMPED  
AS SHOWN, IS 19" ABOVE THE GROUND.  
THE ORIGINAL CORNER STONE, MARKED  
WITH 4 GROOVES ON ONE SIDE, IS  
LYING ALONGSIDE THE IRON PIPE.

Accessories Found: (Condition and Source) THE ORIGINAL  
12" DOUGLAS FIR WHICH BEARS S41°W, 36.3'  
IS DOWN. SCRIBING IS VISIBLE ON PREV-  
IOUSLY OPENED BLAZE. B.T.'S SET BY  
PREVIOUS RENEWAL:

A 12" CEDAR (ORIG. 10") BEARS S67°W, 49.5'  
SCRIBING VISIBLE ON A SINGLE BLAZE, "T30S

#155 ✓

RIW S9CCCSBT"

A 19" DOUGLAS FIR STUMP (ORIG 18")

BEARS S62°E, 38.3', SCRIBING VISIBLE,

ON A SINGLE BLAZE "T30S RIW S10CCCS  
BT"

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) \_\_\_\_\_

A 10" VEW BEARS S17°30'E, 95.1'  
SCRIBED "T30S RIW S10CCCSBT"  
ON A DOUBLE BLAZE

Location and Comments:  
CORNER LIES 500'  
SOUTH OF F.S,  
ROAD NO. 2929

<u>20°E</u>	Compass Declination
<u>U.S. F.S.</u>	Agency
<u>DENNIS GAYLORD</u>	Party Chief
<u>" "</u>	Notekeeper
<u>ROLLAND SIMSHAUSER</u>	Witnesses

OK  
*[Signature]*