

T315 R3W

1/4

53/52

DATE: 10-25-77

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewal #'s #96

Monument(s) Found: (Condition and Source) A 3/4" IRON ROD, BENT OVER.

Accessories Found: (Condition and Source) A 10" NOW 12" DOUGLAS FIR BEARS N62°W 411² FT. WITH PARTIALLY HEALED, BARKED, DOUBLE BLAZE AND VISABLE SCRIBING "CS BT".

#200 ✓

C

RENEWAL

Monument Set: (Procedure and Description) A 5/8" x 30" IRON ROD
WITH 1 1/2" ^{DIA.} ALUM. CAP SET 12 FT. BELOW ROAD SURFACE ELEVATION,
MARKED " DOUGLAS CO.
1/4
53 | 52
1977
SURVEYOR

New Accessories: (Description) A 6" DIA. MAPLE BEARS S29°W
28 1/2 FT., DOUBLE BLAZED AND SCRIBED "1/4 53 CS BT".

Location and Comments:
CORNER IS IN DITCH
OF EXISTING ROAD

<u>20° E</u>	Compass Declination
<u>DC50</u>	Agency
<u>R. B. KIMBERLING</u>	Party Chief
<u>R. B. Kimberling</u>	Notekeeper
<u>M. W. CLINE</u>	Witnesses
<u>S. J. FLAUSE</u>	

OK *[Signature]*